Millway Beach



ADA Transition Plan

July 2021



Institute for Human Centered Design

www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

Background

Millway Beach is located at 399 Millway Road. The beach has three (3) access points, one (1) viewing area, and one (1) parking lot. Two (2) beach access points are sandy paths facing the east side. Another beach access point includes a staircase. The parking lot has 15 parking spaces including two (2) accessible parking spaces. The beach and the parking are only open to residents.

Key Accessibility Issues

• Accessible routes are not maintained in operable working condition.

Note: Millway Beach is not accessible. The topography of the beach prevents the possibility of having an accessible route.

Order of Magnitude Cost Estimates

Total: \$0

Prepared by the Institute for Human Centered Design • www.IHCDesign.org

Town of Barnstable

Millway Beach

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendatio
	Approach and	Entrance	;						

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
А	pproach and E	intrance										
	Exterior Access Route											
1	Parking Lot	Ext.		Exterior Access Route	Exterior		Route not maintained in operable working condition	-	Clear sand to ensure the accessible route is maintained in operable working condition.	1	Labor	\$0
2	Viewing Area East Side	Ext.		Exterior Access Route	Exterior		Route not maintained in operable working condition	-	Clear sand to ensure the accessible route is maintained in operable working condition.	1	Labor	\$0
3	Entrance to Beach Between Parking Lots East Side	Ext.		Exterior Access Route	Sidewalk		Route not maintained in operable working condition	4.2%	Clear sand to ensure the accessible route is maintained in operable working condition.	1	Labor	\$0
А	ccess to Good	s and Se	ervices									
	Ramps											
4	Viewing Area	Ext.		Ramps	Exterior	The second second	Not maintained in operable working condition	-	Clear sand to ensure the ramp surface is	1	Labor	

	-			_	
R	а	m	D	S	

4	Viewing Area East Side	Ext.	Ramps	Exterior	Not maintained in operable working condition	- Clear sand to ensure the ramp surface is maintained in operable working condition.	1	Labor	\$0

Town of Barnstable Millway Beach

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Stairways									· · · · · ·		
5	Staircase Entrance to Beach	Ext.		Stairways	Exterior	N	ot maintained in operable working condition	-	Clear sand from stairs.	1	Labor	\$0
	Benches											
6	Entrance to Beach Between Parking Lots East Side	Ext.		Benches	N/A	No	accessible route to one bench in this area	-	Relocate bench to an accessible route.	1	Labor	\$0
В	est Practice											
	Handrail											
7	Staircase Entrance to Beach	Ext.		Handrail	N/A				Recommend providing return handrail extension to prevent clothing and bags getting caught on handrails.	1	-	\$0