Sandy Neck Beach Gatehouse



Town of Barnstable ADA Transition Plan

August 2021



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

Background

Year Built: 1993

The Sandy Neck Beach Gatehouse is located at 425 Sandy Neck Road in West Barnstable. The building has one (1) gift shop room, one (1) toilet room, one (1) entrance and egress for the public and one (1) staff only entrance/egress. There is a parking lot adjacent to the gate house that has six (6) parking spaces. The parking lot is not striped and has no accessible parking.

Key Accessibility Issues

Parking Lot

Accessibility issues include lack of a van accessible parking space with a marked access aisle and sign and lack of a firm, stable and slip resistant surface at the van accessible space.

Toilet Rooms

Accessibility issues include the toilet located further from the side wall than the maximum allowed, lack of pull-side maneuvering clearance at the exit doors from the toilet rooms and noncompliant toilet paper dispensers. Additional issues include clearance at the toilet seat is less than the minimum required, and mirrors at the lavatory are located higher than the maximum height allowed.

Exterior Ramp

Accessibility issues include lack of edge protection and the handrails are installed less than the minimum required distance from the adjacent surface.

Additional Accessibility Issues

- Threshold is higher than the maximum allowed.
- Application box and sheets box are installed higher than the maximum allowed.

Order of Magnitude Cost Estimates

- Renovate parking lot: \$7,226
- Renovate exterior ramp: \$2,520
- Renovate toilet room: \$6,656
- Miscellaneous corrective actions (threshold): \$150

Total: \$16,552

Town of Barnstable Sandy Neck Beach Gatehouse

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Approach and Entrance												
	Exterior Access Route											
1	Path to Gate House From Parking Lot	Ext.		Exterior Access Route	Exterior		Surface is not stable, firm, and slip-resistant	-	Repair surface. (Cost of 4' wide by 12' long concrete path from access aisle to street crossing.)	1	768	\$768
Off-Street Parking Lot or Garage												
2	Parking Lot	Ext.		Off-Street Parking Lot or Garage	Visitor	T	otal # of parking otal # of designated accessible parking spaces otal # of designated van accessible spaces Surface not stable, firm, and slip-resistant	6 - - -	Provide a compliant van accessible parking space with a marked access aisle. Include a designation sign with the International Symbol of Accessibility (ISA) and the designation "Van Accessible" (Cost for a van accessible space with a concrete surface for the space and access aisle.)	1	6458	\$6458
	Exterior Ram	р										
3	Ramp to Bathhouse Entrance	Ext.		Exterior Ramp	N/A		andrails < 1 1/2" to adjacent surface Edge protection < 4" high	1" - -	Alter the handrails so they are mounted 1-1/2" min. from adjacent surface. Provide edge protection that prevents the passage of a 4" diameter sphere, where any portion of the sphere is within 4" of the finished floor or ground surface.	2	1260	\$2520
	Access to Goods and Services											
Doors, Doorways, & Gates												
4	Toilet Room	1		Doors, Doorways, & Gates	Toilet Room		Maneuvering clearance(s) not provided	11.5"	Provide an automatic door opener.	1	3060	\$3060

Town of Barnstable Sandy Neck Beach Gatehouse

ID	Location	Floor	Room Elemer	t Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
5	Bathhouse Entrance	Ext.	Doors, Doorway & Gates	Emergency s, Egress		Threshold > 1/2" high	1.25"	Alter the threshold to be 1/2" high max.	1	150	\$150
	Operable Parts										
6	Ramp to Bathhouse Entrance	Ext.	Operable Parts	Other	STATE OF STA	Ś. Side reach > 54"	58.75"	Relocate application box so that controls are between 15" - 48" above the finished floor.	1	Labor	\$0
7	Bathhouse Entrance	Ext.	Operable Parts	Other		. Side reach > 54"	57"	Relocate sign in sheets box so that controls are between 15" - 48" above the finished floor.	1	Labor	\$0
	Toilet & Bathing	g Rooms	•								
	Lavatory										
8	Toilet Room	1	Lavatory	N/A		Mirror above lavatory w/reflective surface > 40"	43"	Lower mirror so that the bottom surface is at 40" max. above the finished floor.	1	256	\$256

Town of Barnstable Sandy Neck Beach Gatehouse

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Single-User T	oilet										
9	Toilet Room	1		Single-User Toilet	N/A	. Sid	nterline < or > 18" (MAAB) le or rear grab bar < 33" or > 36" high earance at toilet < 72" clear depth ilet paper dispenser is not compliant	31" - -	Relocate toilet so that the centerline is 18" from the side wall. Mount grab bars 33"- 36" above the floor. Relocate cabinet. Relocate toilet paper so that it is 24" min. high, located under the grab bar, and between 7" and 9" from the front of the toilet.	1	3340	\$3340