Barnstable Dog Park



Town of Barnstable **ADA Transition Plan**

June 2021



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/tty

Background

Barnstable Dog Park is located at 1431 Phinneys Lane, Hyannis. There are three (3) entrances to the dog park. Amenities include a drinking fountains, benches, a route near the park and a parking lot.

Key Accessibility Issues

Exterior Access Route

Accessibility issues include cross slope higher that the maximum allowed at the dog park entrance on the north side. Additional issues include cross and run slopes higher than the maximum allowed at the exterior route near the park. In addition, there is a lack of an accessible route to dog waste bags.

Additional Accessibility Issues

- Parking lot sign installed higher than the maximum allowed.
- Lack of clear floor space at the drinking fountains for seated users.
- Lack of drinking fountain for standing users.

Order of Magnitude Cost Estimates

- ٠

*Total: \$ 18,888

*Cost for exterior route near the park not included.

Best Practice and Inclusive Design

Best practice and inclusive design recommendations include elements that are not required in the standards but may create enhanced experiences for all users.

Renovate exterior access routes: \$720 Drinking fountains for standing users: \$18,168

• Recommend providing a stone dust stable surface around the dog park with no more than 1:50 (2.00%) cross slope and 1:20 (5.00%) run slope that is at least 48" wide and in operable working conditions.

Town of Barnstable Barnstable Dog Park

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Approach and I	Entrance										
	Exterior Access Route											
1	Parking Lot to Dog Park Entrance North Side	Ext.		Exterior Access Route	Walkway	Cr	ross slope > 1:50 (2.00%)		Reduce cross slope to be no steeper than 1:50 (2.00%).	1	240	\$240
2	Route Near the Park	Ext.		Exterior Access Route	Walkway	Cr	ross slope > 1:50 (2.00%)		Reduce cross slope to be no steeper than 1:50 (2.00%).	1	-	\$0
3	Route Near the Park	Ext.		Exterior Access Route	Walkway		ross slope > 1:50 (2.00%) unning slope > 1:20 (5%)	6.6%	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5.00%).	1	-	\$0
4	Route Near the Park	Ext.		Exterior Access Route	Walkway	Cr Ru	ross slope > 1:50 (2.00%) unning slope > 1:20 (5%)	6.3%	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5.00%).	1	-	\$0
5	Route Near the Park	Ext.		Exterior Access Route	Walkway	Ru	unning slope > 1:20 (5%)		Reduce running slope to be no steeper than 1:20 (5.00%).	1	-	\$0

Town of Barnstable Barnstable Dog Park

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Off-Street Parking Lot or Garage											
6	Parking Lot	Ext.		Off-Street Parking Lot or Garage	Visitor	HANDIGAPPED PARKING Lege Special Flate Required Subject Parkins AND Towing It owner? Expense Stood Flate	Sign top > 96" above finished grade	-	Locate sign with the top of the sign 96" above the ground.	1	Labor	\$0
	Access to Goods and Services											
	Dog Parks											
7	Dog Park Entrance Between North and South Side	Ext.		Dog Parks	N/A		Accessible route not provided	-	Ensure an accessible route is provided to dog waste station.	1	240	\$240
8	Dog Park Entrance South Side	Ext.		Dog Parks	N/A		Accessible route not provided	-	Ensure an accessible route is provided to dog waste station.	1	240	\$240
	Additional Access											
	Drinking Fountains											
9	Dog Park Between North and South Side	Ext.		Drinking Fountains	Hi-Lo		Clear floor space not provided No drinking fountain provided for standing users	-	Provide a 30" by 48" clear floor space positioned for a forward approach. Provide an additional drinking fountain for standing users.	1	6056	\$6056

Town of Barnstable Barnstable Dog Park

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
10	Dog Park North Side	Ext.	Drinking Fountains	Hi-Lo		Clear floor space not provided No drinking fountain provided for seated users	-	Provide a 30" by 48" clear floor space positioned for a forward approach. Provide an additional drinking fountain for seated users.	1	6056	\$6056
11	Dog Park 3 South Side	Ext.	Drinking Fountains	Hi-Lo		Clear floor space not provided No drinking fountain provided for seated users	- -	Provide a 30" by 48" clear floor space positioned for a forward approach. Provide an additional drinking fountain for seated users.	1	6056	\$6056
В	est Practice										
12	Route Round the Park	Ext.		N/A			-	Recommend providing a stone dust stable surface around the dog park with no more than 1:50 (2.00%) cross slope and 1:20 (5.00%) run slope that is at least 48" wide and in operable working conditions.	1	-	\$0