### Water Supply Division



Town of Barnstable **ADA Transition Plan** 

September 2021



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

#### Background

The Water Supply Division is located at 47 Old Yarmouth Road in Hyannis. The building is open to the public Monday to Friday from 8:00 AM to 5:00 PM and Saturday in the morning for the payment of water bills. There are seven (7) parking spaces and an electric car charger.

#### **Key Accessibility Issues**

- Lack of a van accessible parking space.
- Lack of maneuvering clearance at the main entrance/exit door.
- Lack of a compliant service counter.
- Lack of an egress sign with raised characters and braille.
- Lack of an illuminated exit sign with the International Symbol of Accessibility (ISA).


#### **Order of Magnitude Cost Estimates**

- ٠ etc.): \$1,868

Total: \$3,718

#### **Best Practice and Inclusive Design**

Best practice and inclusive design recommendations include elements that are not required in the standards but may create enhanced experiences for all users.



Prepared by the Institute for Human Centered Design • www.IHCDesign.org

• Provide a van accessible parking space: \$1,850 Miscellaneous corrective actions (service counter, signage,

 Recommend providing the same information located on the main entrance/exit door at a different location to avoid glare. • Recommend providing an accessible route on both sides of the vehicle spaces that connect to the charging station. • Recommend providing a 30" min. by 48" min. clear floor space at the charging station.

### Town of Barnstable Water Supply Division

11	D Loo	cation	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Approach and Entrance												
	Exterior Access Route												
1	Main Entra	ו ance/Exit	Ext.		Exterior Access Route	Walkway	Level of the second sec	hanges > 1/4"	1.25"	Alter change in level to be 1/4" high max.	1	256	\$256
2	Main Entra	ו ance/Exit	Ext.		Exterior Access Route	Walkway	Level of	hanges > 1/4"	1.25"	See ID #1.	1	-	\$0
	Off-Street Parking Lot or Garage												
3	Park	king Lot	Ext.		Off-Street Parking Lot or Garage			<pre># of parking # of designated accessible parking spaces</pre>	7 0	Provide a van accessible space that is at least 96" wide with a marked access aisle that is at least 96" wide. Provide a sign with the bottom of the sign 60" min. above the ground and the top 96" max. above the ground. Add the designation "Van Accessible" to the sign.	1	1850	\$1850
	Entrance												
4	Main Entra	ו ance/Exit	Ext.		Entrance	Main Entrance	Maneu	uvering clearance is not provided	-	Remove vegetation to ensure the required maneuvering clearance is provided at the door.	1	Labor	\$0
	Access	Access to Goods and Services											

# Town of Barnstable Water Supply Division

ID	Location	Floor Room	1 Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Means of Egress										
5	Lobby	1	Means of Egress	N/A		Tactile exit sign not provided Illuminated ISA symbol not provided (MAAB)	-	Ensure a tactile exit sign with raised characters and braille is provided at exit door. Mount sign between 48"- 60" above the finished floor located on the latch side of the door. Provide an illuminated sign with the International Symbol of Accessibility.	1	432	\$432
	Interior Access Route										
6	Reception Area	1	Interior Access Route			Route < 36" wide	31"	Remove chairs to maintain the required 36" accessible route.	1	Labor	\$0
	Doors, Doorw	/ays, & Gates									
7	Main Entrance/Exit	Ext.	Doors, Doorways, & Gates	, Office		Threshold not beveled Threshold > 1/2" high	2.75"	Bevel the threshold. Alter the threshold to be 1/2" high max.	1	300	\$300
	Signage										
8	Main Entrance/Exit	Ext.	Signage	Informationa I		Sign not maintained in operable working condition	-	Ensure sign is maintained in operable working condition.	1	Labor	\$0

# Town of Barnstable Water Supply Division

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Service Counter										
9	Reception Area	1	Service Counter	N/A		Counter > 36" high	42"	Provide a counter that is 36" max. above the ground or finished floor.	1	880	\$880
	Operable Parts										
10	Charging Station by Parking Lot	Ext.	Operable Parts	Other	Ele	Element not on an accessible route	-	Ensure charging station is located on an accessible route. Recommend providing a 30" min. by 48" min. clear floor space at the charging station. See sketch.	1	Labor	\$0
В	Best Practice										
11	Parking Lot	Ext.						Recommend providing an accessible route on both sides of the vehicle spaces that connect to the charging stations. See sketch.	1	-	\$0
12	Main Entrance/Exit	Ext.		182	Prations BOE 775-0058 MON-FRI B-5			Recommend providing the same information on a different location to avoid glare.	1	-	\$0